To: Matt Francis[m.francis@erllc.com]

From: Way, Steven

Sent: Tue 6/10/2014 10:39:49 PM

Subject: Gold King Photos - GoldKing.portal.pics.docx P1000391.JPG

Matt,

Here are set of photos from the owner that were taken many years ago during the initial operations at the GK. The apparent thickness of the overburden on the face of the hillside is the interesting aspect of these images. You also have the photo that I took a few years ago that I sent, and I attached another angle of the same view.

I will check with

Steve

Steven Way

Federal On-Scene Coordinator

Emergency Response Unit

US EPA - Region 8

1595 Wynkoop Street

Denver, CO 80202

Office: 303-312-6723